Data Sheet

Article number: 586100KDE
Description: Vacuummeter 100-KDE -1 til 0 bar G 1/4
                   Plastic housing - Mounting: Down

Measures

= -	Diameter	= 50	
= -	Glycerin	= No	
= -	Housing material	= Plastic	
= -	Mounting	= Down	
= -	Pressure range	= -1 to 0 bar	
= -	Thread	= G 1/4	
= -			
Application = Vacuum			